
Objectives Identify: Visible dust Paint chips Painted debris Deteriorated paint Record the results on a visual assessment form Module 2: Visual Assessment

Why Perform Visual Assessments? ■ Determines if the area is visibly clean ✓ If the area is not clean, it is less likely to pass dust sampling ■ Required for HUD clearance ✓ Clean up was done properly ✓ Deteriorated paint repaired Module 2: Visual Assessment 2

Steps in a Visual Assessment Walk through sampling area Inside and outside (if applicable) Identify: Visible dust Paint chips Painted debris Deteriorated paint Record results Module 2: Visual Assessment

Location of Visual Assessment Appropriate areas may include: ventire unit and exterior, or vonly areas where work occurred Look at horizontal surfaces vfloors vwindow sills vwindow troughs Module 2: Visual Assessment 4



Dust and Paint Chips/Debris ■ Dust ✓ dust you can see ■ Paint chips ✓ little pieces of paint ■ Painted debris ✓ paint on wood, plaster, or building pieces Module 2: Visual Assessment 6

Why Look for Deteriorated Paint? Deteriorated paint creates dust If the deteriorated paint is leadbased paint, it can cause lead poisoning Module 2: Visual Assessment 7

Deteriorated Paint Any paint that is not intact Chipping Peeling Chalking Cracking Holes, moisture and friction damage Small amounts count! Module 2: Visual Assessment 8

Record Results Be precise about locations Write down results as you go Write down other information Use a form

Summary: Now You Can List the items that should be identified in a visual assessment Identify visible dust, paint chips/debris, deteriorated paint Record results on a visual assessment form

Attachment 2-A: Model of Visual Assessment Form VISUAL ASSESSMENT FORM


Date:	
Address:	
Client:	
Technician:	
Location	Identify visible areas of dust, paint chips, painted debris, and deteriorated paint. (Note location: walls, ceiling, floors, doors, windows, trim, cabinets, etc.)
Entry Area	
Living Room	
Dining Room	
Kitchen	
Common Area	
Bedroom #1	
Bedroom #2	
Bath #1	
Exterior	
Other:	
Other:	


Attachment 2-B: Model of Completed Visual Assessment Form

VISUAL ASSESSMENT FORM

Date of clearance:	8/5/99
Clearance Technician:	JæSmith
Client:	SallyJones
Property address:	78 EastMainSt., Apt. A
	Hammand, IN 89898


Location	Identify visible areas of dust, paint chips, painted debris, and deteriorated paint. (Note location: walls, ceiling, floors, doors, windows, trim, cabinets, etc.)
Entry Area	
Living Room	
Dining Room	
Kitchen	W indow above sirk; deteriorated paint on window sash; C lient said
	deteriorated paintwas tested and is not lead-based paint
Common Area	
Bedroom #1	Eastwindow: deteriorated paint on lower sash and dust and paint drips
Smallbedroom	in trough; C lient said deteriorated paint was tested and is not lead-
(StreetSide)	lased pairt
Bedroom #2	Dustand paint dips on floor
Small bedroom	
(Back of the house)	
Bath #1	
Exterior	














Lead Sampling Technician Course

